COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BD26LJN

Vauxhall Vivaro 3100 2.2 TURBO 150PS PRO

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	62847
Cap Code	VAVI22L1P0VDTM2 4 L

Details

Location	Doncaster	**Fuel Type**	DIESEL	**Body Style**	Panel Van
Reg. date	31/03/2026	**GVW**	3100kg	**Gearbox**	MANUAL
Year	2026	**Colour**	WHITE	**Gears**	6
Mileage	931 Miles Not Warranted	**VIN**	VXEVPFC32SZ109388		

AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS, RACKING IN REAR, DEADLOCKS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Park assist camera
- Air conditioning
- Central locking
- Cruise control
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Front parking sensor
- Auxiliary input socket
- Drivers airbag
- Navigation system
- Digital radio
- Passenger airbag


Photos















30
19
OK?
0
mph
933 mi
RPM x1000


AUTOMOBILES PEUGEOT
VXEVPFC32S2105388
3100 KG
5000 KG
1 – 1575 KG
2 – 1800 KG


AIRBAG


Rhino


Rhino








Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK

ABS light illuminated	OK

Commercial Vehicle Auctions Limited