



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BG19ADV

Iveco Daily 50-150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Livingston

Reg. date 18/04/2019

Year 2019

Mileage 74,244 Miles
Warranted

Fuel Type DIESEL

GVW 5200kg

Colour WHITE

VIN ZCFC150B505218374

Body Style Panel Van LWB

MOT Due 31/01/2027

Gearbox MANUAL

Axle Combi 4x2

ELEVATION PLATFORM NEEDS REPAIRS, CAN NOT BE USED MOT HISTORY SHOW'S MILEAGE IN KM, SIDE LOAD DOOR, WEIGH SYSTEM, KLUBB K42 PL, ELEVATING PLATFORM, REAR VIEW CAMERA.

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4


Features



• Radio/CD

• Front electric windows


• Central locking

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A




2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Cracked
Over 25mm



4: Wing osf
Dented
With Paint Damage



5: Qtr Panel osr
Dented
With Paint Damage



6: Tailgate
Dented
With Paint Damage

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -