

# VEHICLE INSPECTION REPORT

**001589**

## Vlemmix Plant Trailer

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | N/A      |

### Details

|           |            |           |             |            |                   |
|-----------|------------|-----------|-------------|------------|-------------------|
| Location  | Livingston | Mileage   | Not Showing | VIN        | XRUVTA00023001589 |
| Reg. date |            | Fuel Type |             | Body Style | Plant Trailer     |
| Year      |            | Colour    |             |            |                   |

REAR RAMP UNFITTED.

Tyres

NSF

NSR

OSF

OSR

Spare

### Photos



