

VEHICLE INSPECTION REPORT

KX69DDV

ISUZU D-MAX 2.5

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	24961
Cap Code	ISDM25 PDTM4 L

Details

Location	Bedford	GVW	3500kg	Gearbox	MANUAL
Reg. date	22/01/2020	Colour	WHITE	Gears	6
Year	2020	VIN	MPATFS87JKT013826	Axle Combi	4x4
Mileage	30,347 Miles Warranted	Body Style	Access Platform		
Fuel Type	DIESEL	MOT Due	21/01/2027		

PALFINGER P130 PLATFORM (YEAR 2019)

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Park assist camera
- Air conditioning
- Front electric windows