

VEHICLE INSPECTION REPORT

KX68BNY

ISUZU D-MAX 2.5

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	24961
Cap Code	ISDM25 PDTM4 L

Details

Location	Bedford	GVW	3500kg	Gearbox	MANUAL
Reg. date	06/11/2018	Colour	WHITE	Gears	6
Year	2018	VIN	MPATFS87JJT007648	Axle Combi	4x4
Mileage	45,897 Miles Warranted	Body Style	Access Platform		
Fuel Type	DIESEL	MOT Due	05/11/2026		

PALFINGER P130 PLATFORM

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera
- Air conditioning
- Front electric windows