

VEHICLE INSPECTION REPORT

CK25VMG

Vauxhall Vivaro 75kWh Prime

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply
		Cap Id	58141
		Cap Code	VAVI00L27PVE A2 4 L

Details

Location	Doncaster	GVW	3044kg	CAP Clean	£16,500.00
Reg. date	02/05/2025	Colour	WHITE	CAP Average	£15,850.00
Year	2025	VIN	VXEVTZKU9RZ061146	CAP Below	£14,250.00
Mileage	4,205 Miles Warranted	Body Style	Panel Van MWB	Gearbox	AUTOMATIC
Fuel Type	Electric	MOT Due	01/05/2028	Gears	1

TWIN SIDE LOAD DOOR, E/MIRRORS, HEATED SEATS, REAR VIEW CAMERA.

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		