COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MM74FGU

Renault Trafic SL30 90KW 52KWH ADVANCE

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	58415
Cap Code	R1TR00SL3AVE A2 6 L

Details

Location	Doncaster	**Colour**	WHITE	**CAP Average**	£11,700.00
Reg. date	16/12/2024	**VIN**	VF1EL000173518879	**CAP Below**	£10,350.00
Year	2024	**Body Style**	Panel Van SWB	**Gearbox**	AUTOMATIC
Mileage	30,544 Miles Warranted	**Service history**	None	**Gears**	6
Fuel Type	PETROL	**MOT Due**	15/12/2027		
GVW	3070kg	**CAP Clean**	£12,400.00		

SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Rear parking sensor
- USB/iPod interface
- Passenger airbag
- Cruise control
- Auxiliary input socket
- Air conditioning
- Central locking
- Front parking sensor
- Digital radio
- Front electric windows
- Cloth seat trim
- Park assist camera
- Mobile phone App interface
- Drivers airbag

Photos












READY
30544
Active engine
Switch off






RENAULT VEHICLE INNOVATION
STAGE 2
VF1EL000173518879
3070 kg
3990 kg
1 - 1625 kg
2 - 1650 kg



OFF
OFF
SOS


MAX.
110km/h
68mph


samsara



NAULT
E-TECH
ELECTRIC




armorgard










Condition Check



Damage Photos



1: Bumper Front
Chipped
Over 5mm



2: Bonnet
Chipped
Over 5mm



3: Bumper Front
Chipped
Over 5mm



4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Wheel nsf
Scratched
Over 50mm



6: Fuel Flap
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Door nsr
Chipped
Edge Chip



9: Door nsr
Chipped
Edge Chip



10: Door osr
Chipped
Over 5mm



11: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



12: Bumper Front
Chipped
Over 5mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK

Commercial Vehicle Auctions Limited