

VEHICLE INSPECTION REPORT

LR73ZYF

Maxus Deliver 9 2.0 D20 150PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply
		Cap Id	55901
		Cap Code	MXD920LW509DTM2 L

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£11,500.00
Reg. date	12/10/2023	Colour	WHITE	CAP Average	£10,650.00
Year	2023	VIN	LSH14J7C6PA822482	CAP Below	£9,175.00
Mileage	32,826 Miles Warranted	Body Style	Panel Van LWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	11/10/2026	Gears	6

SIDE LOAD DOOR, E/MIRRORS, AD-BLUE.

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Rear parking sensor
- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Carpets Front
Holed
Over 3mm



2: Roof
Dented
With Paint Damage



3: Bumper Front
Chipped
Multiple Chips



4: Bonnet
Dented
Over 30mm



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Badgedecal Rear
Missing
Replace



7: Fuel Flap
Missing
Replace

Interior

Carpet Condition	Poor		Upholstery Condition	Average
Seat Condition	Poor		Odour	No
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake		OK	No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK