

VEHICLE INSPECTION REPORT

FL69XFB

Vauxhall Vivaro 2900 1.5d 100PS Edition

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	44124
		Cap Code	VAVI15191DVDTM2 3 L

Details

Location	Doncaster	Colour	WHITE	CAP Average	£4,450.00
Reg. date	31/12/2019	VIN	VXEVBVHRKL7007098	CAP Below	£3,475.00
Year	2019	Body Style	Panel Van L1	Gearbox	MANUAL
Mileage	91,047 Miles Warranted	Service history	None	Gears	6
Fuel Type	DIESEL	MOT Due	29/07/2027	Axle Combi	4x2
GVW	2830kg	CAP Clean	£5,150.00		

RACKING IN REAR, TWIN SIDE LOAD DOORS, AD-BLUE, E/MIRRORS




Tyres
NSF
NSR
OSF
OSR
Spare

Features

- Bluetooth connection
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Cruise control
- Auxiliary input socket
- Drivers airbag
- Front parking sensor
- Digital radio
- Passenger airbag
- Park assist camera
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Sill ns
Dented
With Paint Damage



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

4: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK