

VEHICLE INSPECTION REPORT

C430119

MONTRACON CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Doncaster	Colour	RED	Brakes	Drum
Reg. date	01/01/2016	VIN	SMRC3AXXXGN117834	Axle Combi	Tri
Year	2016	Body Style	Trailer	Rear Suspension	Air
Mileage	Not Showing	Service history	None	Rear Doors	Barn
Fuel Type		MOT Due	05/11/2026		

SAF AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF
NSR
OSF
OSR
Spare