



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SJ19ZZM

Nissan Navara N-GUARD 2.3 DCI 190PS

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	43551
Cap Code	NINA23NGUA7DTA4 4 L

Details

Location	Doncaster	Colour	BLACK	CAP Below	£5,975.00
Reg. date	01/03/2019	VIN	VSKCTND23U0118698	Gearbox	AUTOMATIC
Year	2019	Body Style	Pickup Double Cab	Gears	7
Mileage	122,896 Miles Not Warranted	MOT Due	23/10/2026	Axle Combi	4x4
Fuel Type	DIESEL	CAP Clean	£8,875.00		
GVW	3045kg	CAP Average	£7,675.00		

ENGINE NOISE AD-BLUE, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR




Spare


Features

- Bluetooth connection
- Cruise control
- Navigation system
- Park assist camera
- Rear parking sensor
- Auxiliary input socket
- Digital radio
- Air conditioning
- Front electric windows
- Rear electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Leather seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



3: Wing nsf
Chipped
Over 5mm



4: Door nsf
Chipped
Over 5mm



5: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel nsr
Rusted
Over 5mm



7: Tailgate
Scratched
Up To 25mm Thru Paint



8: Door osr
Chipped
Multiple Chips



9: Door osf
Chipped
Multiple Chips



10: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	Fault	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		