

VEHICLE INSPECTION REPORT

C302900

CARTWRIGHT CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Avonmouth	Colour	BLACK	Axle Combi	Tri
Reg. date	01/01/2010	VIN	100211	Rear Suspension	Air
Year	2010	Body Style	Trailer	Rear Doors	Barn
Mileage	Not Showing	MOT Due	Expired		
Fuel Type		Brakes	Drum		

BPW AXLES, RAISE & LOWER VALVE

Tyres

NSF
NSR
OSF
OSR
Spare

Photos





