

VEHICLE INSPECTION REPORT

YD19YCN

Fiat Ducato 35 2.3 Multijet II 130PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Code	FIDU2335L3BDTM2 5 L

Details

Location	Doncaster	Colour	YELLOW	Last service date	06/01/2026
Reg. date	01/03/2019	VIN	ZFA25000002J28998	MOT Due	05/03/2027
Year	2019	Body Style	Curtainside	Gearbox	MANUAL
Mileage	173,044 Miles Not Warranted	Service history	Yes	Gears	6
Fuel Type	DIESEL	Service documents	Service Book	Tail Lift	Column
GVW	3500kg	Number of stamps	9		

E/MIRRORS, AD-BLUE

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Bluetooth connection
- Front electric windows
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Central locking
- Air conditioning
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Dented
With Paint Damage



3: Door Mirror Assy nsf
Broken
Replace



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsf
Chipped
Over 5mm



6: Door Moulding nsf
Missing
Replace



7: Wing osf
Chipped
Over 5mm



8: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		