

VEHICLE INSPECTION REPORT

YK21EMW

VOLKSWAGEN CRAFTER CR35 2.0 TDI 177PS Trendline

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Present		
		Cap Id	42214		
		Cap Code	VWCR205L7THDTA2 1 L		
Details					
Location	Doncaster	VIN	WV1ZZZSYZM9062414	MOT Due	Expired
Reg. date	20/07/2021	Body Style	Panel Van LWB	CAP Clean	£5,850.00
Year	2021	Service history	Yes	CAP Average	£5,200.00
Mileage	204,080 Miles Not Warranted	Service documents	Service Book	CAP Below	£4,250.00
Fuel Type	DIESEL	Number of stamps	8	Gearbox	AUTOMATIC
GVW	3500kg			Gears	8
Colour	WHITE	Last service date	28/07/2025		
		Last service miles	193,964		

COLLECTED AS NON RUNNER - TURBO ISSUES, ONLY RUNS ON BOOST PACK, WARNING LIGHTS ON DASH, HEAVY SMOKING HONDA GX 240 GENERATOR, E/MIRRORS, AD-BLUE

Tyres




NSF
NSR
OSF
OSR
Spare

Features

- Navigation system
- Front electric windows
- Rear parking sensor
- Central locking
- Digital radio
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Badgedecal Front
Broken
Replace



3: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	Fault
EML light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK		