

VEHICLE INSPECTION REPORT

DN73HTV

Vauxhall Vivaro 2900 1.5d 100PS Prime

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	56177
		Cap Code	VAVI1519P1VDTM2 3 L

Details

Location	Livingston	GVW	2900kg	CAP Clean	£11,000.00
Reg. date	31/10/2023	Colour	WHITE	CAP Average	£10,200.00
Year	2023	VIN	VXEVBVHRMP7867067	CAP Below	£8,775.00
Mileage	33,183 Miles Not Warranted	Body Style	Panel Van L1	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	30/10/2026	Gears	6

WARNING LIGHTS ON DASH SIDE LOAD DOOR, ROOF RACK, E/MIRRORS.


Tyres

NSF
NSR
OSF
OSR
Spare

Features


- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK

Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK