COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DA21GXL

Man TGL 12.220

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	**GVW**	12000kg	**Cab Type**	CREW CAB
Reg. date	21/06/2021	**Colour**	YELLOW	**Gearbox**	AUTOMATIC
Year	2021	**VIN**	WMA14DZZ4MY431209	**Axle Combi**	4x2
Mileage	481,573 Km Warranted	**Body Style**	Recovery	**Rear Suspension**	Air
Fuel Type	DIESEL	**MOT Due**	28/02/2027		

INFOTAINMENT SCREEN INOP BONIFACE STVLA+SCL DEMOUNT SLIDE BODY (YEAR 2021), SPEC LIFT, SLIDING WINCH, DNYA CYCLE, 3PT SEAT BELTS, UNDERSEAT STORAGE

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Digital radio
- Cloth seat trim
- Air conditioning

Photos









Commercial Vehicle Auctions Limited

DA21 GXL

BONIFACE
WARNING

MODEL
SERIAL No.
BUILD SHEET
TEST No.
DATE






FIRST AID

BONIFACE
IN
OUT
WINCH
BONIFACE

Condition Check



Damage Photos

1: Bumper Front
Cracked
Over 25mm

2: Bumper Front
Chipped
Multiple Chips

3: Bumper Front
Cracked
Over 25mm

4: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

5: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	-
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK