

VEHICLE INSPECTION REPORT

BX10FSS

DAF LF 45.180

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Code	999900

Details

Location	Bedford	Colour	WHITE	Axle Combi	4x2
Reg. date	01/08/2010	VIN	XLRAE45FF0L358321	Rear Suspension	Steel
Year	2010	Body Style	Box Van	Rear Doors	Roller
Mileage	273,967 Km Warranted	MOT Due	31/10/2027	Tail Lift	Column
Fuel Type	DIESEL	Cab Type	DAY CAB		
GVW	10000kg	Gearbox	MANUAL		

WORK STATION IN REAR, SINGLE SIDE BARN DOOR

Tyres

NSF
NSR
OSF
OSR
Spare