

VEHICLE INSPECTION REPORT

AX15SGU

Nissan NV200 1.5 dCi 110 Acenta DCI

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply
		Cap Id	30774
		Cap Code	NINV15AC1 VDTM2 L

Details

Location	Doncaster	GVW	2000kg	CAP Clean	£940.00
Reg. date	18/05/2015	Colour	WHITE	CAP Average	£780.00
Year	2015	VIN	VSKYBAM20U0098288	CAP Below	£550.00
Mileage	182,231 Miles Not Warranted	Body Style	Panel Van	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	Expired	Gears	5

TWIN SIDE LOAD DOOR, AD-BLUE


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Cloth seat trim
- Front electric windows
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Chipped
Multiple Chips



3: Sill ns
Dented
With Paint Damage



4: Sill ns
Dented
With Paint Damage



5: Qtr Panel nsr
Chipped
Multiple Chips



6: Door nsr
Chipped
Multiple Chips



7: Door osr
Chipped
Multiple Chips



8: Qtr Panel osr
Dented
With Paint Damage



9: Qtr Panel osr
Chipped
Multiple Chips



10: Qtr Panel osr
Chipped
Multiple Chips



11: Sill os
Dented
With Paint Damage



12: Sill os
Dented
With Paint Damage



13: Door osf
Chipped
Multiple Chips



14: Door osf
Dented
With Paint Damage



15: Wing of
Dented
With Paint Damage



16: Screen Front
Scratched
Over 30mm



17: Carpets Front
Holed
Over 3mm



18: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		