

VEHICLE INSPECTION REPORT

PG66UEV

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Doncaster

Reg. date 27/02/2017

Year 2017

Mileage 1,153,696 Km
Warranted

Fuel Type DIESEL

GVW 44000kg

Colour RED

VIN XLRTGM4100G148133

Body Style Tractor Unit

Service history Part

Number of stamps 14

Last service date 24/12/2025

Last service miles 1,058,534

MOT Due 31/12/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3



OSO4

Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Number Plate Front
Broken
Replace



3: Panel Front
Cracked
Replace



4: Wing nsf
Cracked
Replace



5: Door nsf
Dented
With Paint Damage



6: Door nsf
Dented
With Paint Damage



7: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Panel Rear
Dented
With Paint Damage



10: Qtr Panel Trim os
Broken
Replace



11: Qtr Panel Moulding os
Broken
Replace

Interior

Carpets Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK