



COMMERCIAL VEHICLE AUCTIONS LTD  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

## VEHICLE INSPECTION REPORT

PE17HNV

### Daf CF 440

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

#### Details

Location Doncaster

Reg. date 06/03/2017

Year 2017

Mileage 1,314,754 Km  
Warranted

Fuel Type DIESEL

GVW 44000kg

Colour RED

VIN XLRTGM4100G149348

Body Style Tractor Unit

Service history Full

Number of stamps 13

Last service date 22/01/2026

Last service miles 1,233,710

MOT Due 30/09/2027

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

#### Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3



OSO4


### Features

- Bluetooth connection
- Radio/CD
- Cloth seat trim
- Cruise control
- Air conditioning
- Auxiliary input socket
- Front electric windows
- Digital radio
- Central locking


### Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front Moulding  
Missing  
Replace



3: Bumper Front  
Dented  
With Paint Damage



4: Door nsf  
Chipped  
Multiple Chips



5: Wing nsf  
Scratched  
Over 25mm Thru Paint



6: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
Over 100mm



7: Door osf  
Dented  
With Paint Damage



8: Screen Front  
Chipped  
Over 10mm

**Interior**

|                       |    |                                     |    |
|-----------------------|----|-------------------------------------|----|
| Carpet Condition      | OK | Upholstery Condition                | OK |
| Seat Condition        | OK | Odour                               | -  |
| Engine Runs           | OK | No Excessive Smoking                | OK |
| EML light illuminated | OK | Oil warning light illuminated       | OK |
| ABS light illuminated | OK | DPF light illuminated               | OK |
|                       |    | Service indicator light illuminated | OK |