COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK71UVW

Man TGL 12.220

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	**GVW**	12000kg	**Cab Type**	CREW CAB
Reg. date	07/12/2021	**Colour**	YELLOW	**Gearbox**	AUTOMATIC
Year	2021	**VIN**	WMA14DZZ0MY432518	**Axle Combi**	4x2
Mileage	580,533 Km Warranted	**Body Style**	Recovery	**Rear Suspension**	Air
Fuel Type	DIESEL	**MOT Due**	31/01/2027		

BONIFACE STVLA+SCL DEMOUNT SLIDE BODY (YEAR 2021) C/W REMOTE, SPEC LIFT, SLIDING WINCH, DNYA CYCLE, 3 POINT SEAT BELTS, UNDERSEAT STORAGE

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features


- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Digital radio
- Cloth seat trim
- Air conditioning

Photos

































Commercial Vehicle Auctions Limited


MODEL: ST VLA + SCC
SERIAL No.: 11-20617-21
BUILD SHEET: 20617
TEST No.: 3724
DATE: 22.11.2021
BED (KDC)
SECOND CAR LIFT
RATING TEST SWL
5000 6400 5000
2000 2800 2000
BONIFACE ENGINEERING LTD
KINGLEY WAY
FISON WAY INDUSTRIAL EST
THETFORD NORFOLK IP24 1HZ
TEL: +44 (0) 1842 754222
FAX: (0) 1842 765615

BK71UVW









BONIFACE
IN
BED
WINCH
BONIFACE


Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips



2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel Moulding ns
Scuffed (Unpainted)
UpTo 100mm



6: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



7: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK