COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK71UVU

Man TGL 12.220

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	**GVW**	12000kg	**Cab Type**	CREW CAB
Reg. date	27/10/2021	**Colour**	YELLOW	**Gearbox**	AUTOMATIC
Year	2021	**VIN**	WMA14DZZ0MY432406	**Axle Combi**	4x2
Mileage	471,193 Km Warranted	**Body Style**	Recovery	**Rear Suspension**	Air
Fuel Type	DIESEL	**MOT Due**	30/09/2027		

BONIFACE STVLA + SCL DEMOUNT SLIDE BODY (YEAR 2021) C/W REMOTE, SPEC LIFT, SLIDING WINCH, DYNA CYCLE, 3 POINT SEATBELTS, UNDERSEAT STORAGE

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Digital radio
- Cloth seat trim
- Air conditioning

Photos










RIO
LITE-wire
PULSE

MODE
D
R

Driver & Vehicle Standards Agency
Plate
Vehicle Identification No.
WMA14DZZ0MY432406
MAN /TGL
RIGID R
27/10/21
2021
12000
12000
4700
4700
8700
8700
10345
2500
DEPARTMENT FOR TRANSPORT
GREAT BRITAIN
24/03/22
REPLACEMENT

MAN Truck & Bus SE
WMA14DZZ0MY432406





SAFE WORKING LOAD OF WINCH AND CABLE = 3560KG
















BONIFACE





Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Chipped
Multiple Chips



4: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



5: Door nsr
Chipped
Multiple Chips



6: Door osf
Scratched
Over 25mm Not Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK