

# VEHICLE INSPECTION REPORT

**AV68BLF**

## JOHN DEERE X949

### Inspection

### Vehicle

|          |          |
|----------|----------|
| VAT      | Plus VAT |
| V5       | Present  |
| Cap Code | 999900   |

### Details

|           |            |           |                         |            |                   |
|-----------|------------|-----------|-------------------------|------------|-------------------|
| Location  | Bedford    | Mileage   | 777 Hours Not Warranted | VIN        | 1M0X949AEJM060115 |
| Reg. date | 09/10/2018 | Fuel Type | DIESEL                  | Body Style | Ride on Mower     |
| Year      | 2018       | Colour    | GREEN/YELLOW            | Gearbox    | HYDROSTATIC       |

### Tyres

|       |
|-------|
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |

### Photos



