

VEHICLE INSPECTION REPORT

AV68BLJ

JOHN DEERE X949

Inspection

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Bedford	Mileage	534 Hours Not Warranted	VIN	1M0X949ACJM060124
Reg. date	09/10/2018	Fuel Type	DIESEL	Body Style	Ride on Mower
Year	2018	Colour	GREEN/YELLOW	Gearbox	HYDROSTATIC

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



