

VEHICLE INSPECTION REPORT

E11437

DOOSAN DX27Z

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Doncaster	Mileage	1,557 Hours Not Warranted	VIN	DBMB4BBKKL0E11437
Reg. date	01/01/2020	Fuel Type	Diesel	Body Style	Excavator
Year	2020	Colour		Gearbox	Hydrostatic

QUICK HITCH, HAMMER PIPE WORK

Tyres

NSF

NSR



OSF

OSR

Spare

Photos







Commercial Vehicle Auctions Limited