

VEHICLE INSPECTION REPORT

LK16HJU

KUBOTA G26

Non Runner

Inspection

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Bedford	Mileage	Not Showing	VIN	G26HD63524
Reg. date	19/08/2016	Fuel Type	DIESEL	Body Style	Ride on Mower
Year	2016	Colour	ORANGE	Gearbox	HYDROSTATIC

NON RUNNER-DOES NOT POWER UP

Tyres

NSF
NSR
OSF
OSR
Spare