

VEHICLE INSPECTION REPORT

KX67CGF

KUBOTA G26

Inspection

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Bedford	Mileage	226 Hours Not Warranted	VIN	G26HD63908
Reg. date	01/11/2017	Fuel Type	DIESEL	Body Style	Ride on Mower
Year	2017	Colour	ORANGE	Gearbox	HYDROSTATIC

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	