

VEHICLE INSPECTION REPORT

C338732

DON BUR BOX DOUBLE DECK

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Bedford	Colour	RED	Axle Combi	Tri
Reg. date	01/01/2013	VIN	SEPBV38GHDL060716	Rear Suspension	Air
Year	2013	Body Style	Trailer	Rear Doors	Roller
Mileage	Not Showing	MOT Due	30/04/2027		
Fuel Type		Brakes	Disc		

CORROSION BPW AXLES, FERRY LASHING RINGS

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



