

# VEHICLE INSPECTION REPORT

**BU14SYC**

## Setra S416 GT-HD

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

### Details

Location Doncaster

Reg. date 03/04/2014

Year 2014

Mileage 533,990 Km Not Warranted

Fuel Type DIESEL

GVW 24000kg

Colour GOLD

VIN WKK63213423114319

Body Style Coach

Service history None

MOT Due 26/02/2027

Cab Type CREW CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Rear Suspension Air

\*5% BUYERS FEE\* 53 SEATS + DRIVER + CREW RECLINING SEATS WITH ARM RESTS LAP BELTS, CONTINENTAL SIDE DOOR ENTERTAINMENT SYSTEM, PA SYSTEM FULL WIDTH UNDERBODY STORAGE

### Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

Punctured

NSO3

NSO4

OSO1

OSO2


OSO3


OSO4

## Features

- Bluetooth connection
- Digital radio
- Metallic Paint
- Cruise control
- Radio/CD
- Cloth seat trim
- Park assist camera
- Air conditioning
- Auxiliary input socket
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Screen Front  
Chipped  
Over 10mm



2: Roof  
Scratched  
Over 25mm Thru Paint



3: Bonnet  
Chipped  
Multiple Chips




4: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



5: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



6: Other  
N/A  
N/A



7: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



8: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



9: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



10: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



11: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



12: Wing osf  
Scratched  
Over 25mm Thru Paint

Interior

|                       |    |                       |    |
|-----------------------|----|-----------------------|----|
| Carpets Condition     | OK | Upholstery Condition  | OK |
| Seat Condition        | OK | Odour                 | -  |
| Engine Runs           | OK | No Excessive Smoking  | OK |
| EML light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK |                       |    |