

# VEHICLE INSPECTION REPORT

**HX19XEH**

## MERCEDES-BENZ CITAN 109 CDI

### Inspection

### Vehicle

|          |                  |
|----------|------------------|
| VAT      | Plus VAT         |
| V5       | Present          |
| Cap Id   | 26515            |
| Cap Code | MECL159C VDTM2 L |

### Details

|           |                            |            |                   |             |           |
|-----------|----------------------------|------------|-------------------|-------------|-----------|
| Location  | Bedford                    | GVW        | 1950kg            | CAP Clean   | £2,600.00 |
| Reg. date | 28/03/2019                 | Colour     | WHITE             | CAP Average | £2,225.00 |
| Year      | 2019                       | VIN        | WDF4156032U258392 | CAP Below   | £1,750.00 |
| Mileage   | 108,043 Miles<br>Warranted | Body Style | Panel Van LWB     | Gearbox     | MANUAL    |
| Fuel Type | DIESEL                     | MOT Due    | 27/03/2027        | Gears       | 5         |

E/MIRRORS, SINGLE SIDE LOAD DOOR

Tyres

NSF

NSR

OSF

OSR

Spare

## Features

• Air conditioning

• Front electric windows

## Photos



