

VEHICLE INSPECTION REPORT

C279295

SDC BOX DOUBLE DECK STEPFRAME

Inspection	Vehicle
VAT	Plus VAT
V5	N/A

Details

Location	Bedford	Fuel Type		Brakes	Drum
Reg. date	01/01/2009	Colour	BLUE	Axle Combi	Tri
Year	2009	VIN	SDCPL45B300104379	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn

BPW AXLES, RAISE & LOWER VALVE

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



