

VEHICLE INSPECTION REPORT

LN65UYA

DAF CF 220

Inspection

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Bedford	GVW	18000kg	Gearbox	AUTOMATIC
Reg. date	28/01/2016	Colour	WHITE	Axle Combi	4x2
Year	2016	VIN	XLRAEM3700G091072	Rear Suspension	Air
Mileage	347,899 Km Warranted	Body Style	Box Van	Rear Doors	Roller
Fuel Type	DIESEL	Cab Type	SLEEPER CAB	Tail Lift	Column

SURROUND CAMERA SYSTEM

Tyres







NSF	
NSR	
OSF	
OSR	
Spare	


Features

- Air conditioning

Photos







Commercial Vehicle Auctions Limited