

VEHICLE INSPECTION REPORT

PP4564

MECALAC TA6

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Doncaster	Mileage	Not Showing	VIN	
Reg. date	01/01/2018	Fuel Type		Body Style	Demount chassis
Year	2018	Colour	YELLOW		

6TONNE SITE DUMPER

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



