

# VEHICLE INSPECTION REPORT

**DK17KYZ**

## Man TGM 18.290

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date	14/06/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMAN18ZZ4HY355000	Gearbox	MANUAL
Mileage	180,759 Km Warranted	Body Style	Dropside & Crane	Axle Combi	4x2
Fuel Type	DIESEL	MOT Due	Expired	Rear Suspension	Air

\*MOT HISTORY INCORRECTLY RECORDED IN KM/MILES\* HMF 1420K-AC REMOTE CRANE (YEAR 2017)

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Bluetooth connection
- Cruise control
- Park assist camera
- Digital radio
- Front electric windows
- Cloth seat trim

## Photos












## Condition Check



## Damage Photos



1: Bumper Front  
Scratched  
Over 100mm Thru Paint



2: Bonnet  
Chipped  
Multiple Chips





3: Panel Front  
Scratched  
Over 25mm Thru Paint



4: Bumper Front  
Scratched  
Over 100mm Thru Paint



5: Wing nsf  
Scratched  
Over 25mm Thru Paint



6: Door osf  
Scratched  
Over 25mm Thru Paint



7: Seat Base Cover osf  
Holed  
Over 3mm

## Interior

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	Poor	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		