

# VEHICLE INSPECTION REPORT

**C007463**

## CARTWIRGHT BOX

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | N/A      |

### Details

|           |             |            |         |                 |        |
|-----------|-------------|------------|---------|-----------------|--------|
| Location  | Bedford     | Fuel Type  |         | Axle Combi      | Tandem |
| Reg. date | 01/01/1999  | Colour     | RED     | Rear Suspension | Air    |
| Year      | 1999        | VIN        |         | Rear Doors      | Roller |
| Mileage   | Not Showing | Body Style | Trailer |                 |        |

\*CORROSION\* ROR AXLES

### Tyres

|       |
|-------|
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |