

# VEHICLE INSPECTION REPORT

**BF68EHY**

## Mercedes-Benz Citan 109 CDI

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 21/09/2018

Year 2018

Mileage 72,491 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN WDF4156032U253452

Body Style Panel Van

MOT Due Expired

CAP Clean £3,625.00

CAP Average £3,150.00

CAP Below £2,450.00

Gearbox MANUAL

\*COLLECTED AS NON RUNNER\* SIDE LOAD DOOR, E/ MIRRORS

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Door nsf  
Dented  
Over 30mm

No Image



3: Qtr Panel nsr  
Dented  
With Paint Damage

4: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



5: Door nsr  
Chipped  
Multiple Chips



6: Qtr Panel osr  
Dented  
With Paint Damage



7: Door osf  
Dented  
Over 30mm



8: Seat Base Cover osf  
Holed  
Over 3mm

## Interior

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	Poor	<b>Odour</b>	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		