

# VEHICLE INSPECTION REPORT

**YK12GPZ**

## VOLVO FE 300

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | Present  |

### Details

|           |                          |                 |                   |                 |        |
|-----------|--------------------------|-----------------|-------------------|-----------------|--------|
| Reg. date | 06/07/2012               | VIN             | YV2VH70C8CB626153 | Gearbox         | MANUAL |
| Year      | 2012                     | Body Style      | Curtainside       | Axle Combi      | 6x2    |
| Mileage   | 585,511 Km Not Warranted | Service history | Yes               | Rear Suspension | Air    |
| Fuel Type | Diesel                   | MOT Due         | 30/09/2025        | Rear Doors      | Barn   |
| Colour    | WHITE                    | Cab Type        | DAY CAB           |                 |        |

\*ENGINE NOISE\* REAR LIFT

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Park assist camera

## Photos



