

VEHICLE INSPECTION REPORT

WR63SYF

VAUXHALL MOVANO 2.3 CDTI H2 Van 125ps

Cat: S
Inspection

Vehicle

VAT

V5 To Follow

Details

| | | | | | |
|-----------|----------------------------|------------|-------------------|-----------------|--------|
| Reg. date | 23/12/2013 | VIN | W0LMRF4DECB045469 | Gearbox | MANUAL |
| Year | 2013 | Body Style | Panel Van MWB | Gears | 6 |
| Mileage | 115,891 Miles Warranted | Keys | 1 | Doors | 2 |
| Fuel Type | Diesel | MOT Due | Expired | Steering Combi | Steer |
| Colour | SILVER | Cab Type | DAY CAB | Rear Suspension | Steel |

Category S Insurance Loss. Vehicle Structurally Damaged But Repairable-Insurer Decided Not to Repair.

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Rear parking sensor
- Drivers airbag
- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim
- Metallic Paint