

VEHICLE INSPECTION REPORT

LC23DPW

Citroen Berlingo 1.5 BlueHDi 1000Kg Enterprise Ed 100ps 6 Speed S/S

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 31/08/2023

VIN VR7EFYHT2PJ764462

Gears 6

Year 2023

Body Style Panel Van SWB

Steering Combi Steer

Mileage 11,264 Miles Not Warranted

Keys 2

Rear Suspension Steel

MOT Due 30/08/2026

Fuel Type Diesel

Gearbox MANUAL

Colour WHITE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Front electric windows
- Rear parking sensor
- Drivers airbag
- Radio/CD
- Central locking
- Air conditioning
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	Yes

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK