COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

WG61HXF

Land Rover Defender TDCi 2.2 110PS

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Buyer To Apply
Cap Id	21896
Cap Code	LRDE22110 EDTM4 1 L

Details

Location	Doncaster	**GVW**	3050kg	**Gearbox**	MANUAL
Reg. date	16/01/2012	**Colour**	WHITE	**Gears**	6
Year	2012	**VIN**	SALLDHMP7CA416731	**Axle Combi**	4x4
Mileage	10,466 Miles Warranted	**Body Style**	SUV		
Fuel Type	DIESEL	**MOT Due**	06/11/2026		

6 SEATS + DRIVER

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim

Photos










MPH km/h
10466


LAND ROVER
PAINT
TRIM





WG61
HXF




WG61
HXF








Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Rusted
Over 5mm



3: Wing nsf
Dented
Over 30mm



4: Door nsf
Chipped
Multiple Chips



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Door osf
Chipped
Multiple Chips

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK