

VEHICLE INSPECTION REPORT

YK68EDM

Ford Ranger XL 2.2 TDCi 160PS

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	34996
Cap Code	FORA22SXL PDTM4 5 L

Details

Location	Livingston	GVW	2925kg	CAP Clean	£2,425.00
Reg. date	28/02/2019	Colour	WHITE	CAP Average	£2,050.00
Year	2019	VIN	6FPGXXMJ2GJU02261	CAP Below	£1,600.00
Mileage	202,437 Miles Warranted	Body Style	Pickup Single Cab	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	04/12/2026	Gears	6

***NON-RUNNER, ENGINE BLOWN* OUTSTANDING RECALL, TOW BAR, E/MIRRORS**

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips

No Image



3: Badgedecal Front
Missing
Replace

4: Bumper Front Grill
Broken
Replace



5: Bumper Front
Cracked
Over 25mm



6: Bumper Front
Chipped
Multiple Chips



7: Sill os
Rusted
Over 5mm



8: Door osf
Chipped
Multiple Chips



9: Qtr Panel osr
Hole
Over 10mm



10: Qtr Panel osr
Poor Previous Repair
Poor Paint



11: Tailgate
Rusted
Over 5mm



12: Qtr Panel nsr
Rusted
Over 5mm



13: Qtr Panel nsr
Chipped
Multiple Chips



14: Door nsf
Dented
Over 30% Of Panel



15: Qtr Panel nsr
Dented
With Paint Damage

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Poor		Poor	
Average		No	
Engine Runs	Fault	Gearbox 1st and Reverse Test	Fault
Brakes	Fault	Clutch Slip Test from Static	Fault
Turbo Boosting	Fault	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	Fault	No Excessive Smoking	Fault
EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	Fault	Service indicator light illuminated	Fault