COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

AY72UVW

Volvo FL 250

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	**GVW**	14000kg	**MOT Due**	31/05/2027
Reg. date	07/10/2022	**Colour**	YELLOW	**Cab Type**	CREW CAB
Year	2022	**VIN**	YV2T0X1A3NZ142977	**Gearbox**	AUTOMATIC
Mileage	490,301 Km Warranted	**Body Style**	Recovery	**Axle Combi**	4x2
Fuel Type	DIESEL	**Service history**	None	**Rear Suspension**	Air

BONIFACE STVLA+SCL DEMOUNT SLIDE BODY (YEAR 2022) C/W REMOTE, SPEC LIFT, SLIDING WINCH, DYNA CYCLE, 3 POINT SEATBELTS, UNDERSEAT STORAGE

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Auxiliary input socket
- Central locking
- Digital radio
- Cloth seat trim

Photos













Volvo Truck Corporation
96/53/EC article10B
Compliant


AY72 UVM

MODEL: 6T VLA + SCL
SERIAL No.: 08-20645-22
BUILD SHEET: 20645
TEST No. 3799
DATE: 30:08:2022
RATING TEST SWL
BED (UDL) 6000 7200 6000
SECOND CAR LIFT 2000 2000 2000
CE UK CA
BONIFACE ENGINEERING LTD
HOWLETT WAY
FISON WAY INDUSTRIAL EST
THETFORD NORFOLK IP24 1HZ
TEL: +44 (0) 1842 754232
FAX: (0) 1842 765619












BONIFACE

BONIFACE








FIRST AID







Condition Check



Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



4: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK