COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BP70DKX

Iveco S-Way 440

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Doncaster	**Colour**	WHITE	**Gearbox**	AUTOMATIC
Reg. date	07/01/2021	**VIN**	WJMS62NUZ0C440941	**Axle Combi**	6x2
Year	2021	**Body Style**	Tractor Unit	**Steering Combi**	Mid-Lift
Mileage	329,005 Km Not Warranted	**Service history**	None	**Rear Suspension**	Air
Fuel Type	DIESEL	**MOT Due**	31/01/2027		
GVW	44000kg	**Cab Type**	AS SLEEPER CAB		

WARNING LIGHT ON DASH SLIDING 5TH WHEEL

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Front electric windows
- Cruise control
- Drivers airbag
- Digital radio
- Central locking
- Air conditioning
- Cloth seat trim

Photos












14:16 0km/h
329006.0km

D
N
R



Plate
REPLACEMENT

IVECO MAGIRUS AG
WJM562NUZ0C440941
26000 kg
50000 kg
AD3C
2640 1360
IVECO




IVECO









Condition Check




Damage Photos



1: Bumper Front
Dented
With Paint Damage



2: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



3: Qtr Panel nsr
Chipped
Multiple Chips



4: Qtr Panel osr
Chipped
Multiple Chips

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Turbo Boosting	OK		
Parking Brake	OK		
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK