

VEHICLE INSPECTION REPORT

ST13NMV

Ford Transit Connect Low Roof Van TDCi 75ps

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 06/08/2013

Year 2013

Mileage 76,844 Miles
Warranted

Fuel Type Diesel

Colour YELLOW

VIN WF0TXXTTPTDB59052

Body Style Panel Van SWB

Keys 1

MOT Due 23/08/2025

Gearbox MANUAL

Gears 5

Doors 2

Steering Combi Steer

single side door

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Radio/CD
- Front electric windows
- Drivers airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Sill os
Scratched
Over 25mm Thru Paint



2: Bonnet
Dented
With Paint Damage



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Door osf
Dented
Over 2 UpTo 10mm



5: Qtr Panel osr
Rusted
Over 5mm



6: Bumper Rear
Rusted
Over 5mm



7: Tailgate
Rusted
Over 5mm



8: Door nsr
Dented
Over 30mm

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK