COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

KX19AWU

Isuzu D-Max 2.5 TD

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	ISDM25 PDTM4 L

Details

Location	Doncaster	**GVW**	3500kg	**Service documents**	Printout
Reg. date	01/05/2019	**Colour**	WHITE	**Last service date**	10/03/2026
Year	2019	**VIN**	MPATFS87JJT008362	**MOT Due**	12/03/2027
Mileage	70,131 Miles Warranted	**Body Style**	Access Platform	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service history**	Yes	**Gears**	6

AD-BLUE, CPL PALFINGER P130 PLATFORM (YEAR 2019), E/ MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Park assist camera
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking
- Front electric windows
- Cloth seat trim


Photos




















RANGE
120
miles
MPH


ISUZU MOTORS LTD.
e4*2007/46*0413
MPATFS87JJT008362
GVW 3050 kg
GCW 6000 kg
AXLE 1 1350 kg
AXLE 2 1870 kg







LOLER SERVICE RECORD
CPL
WARNING
DANGER






2.6 Metres (8'-5")




KX19 AWU












Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Not Thru Paint



2: Wing nsf
Scratched
Over 25mm Not Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



4: Door nsf
Scratched
Over 25mm Thru Paint



5: B Post ns
Scratched
Over 25mm Thru Paint



6: Door osf
Dented
With Paint Damage



7: Wing osf
Scratched
Over 25mm Thru Paint



8: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



9: Seat Base Cover osf
Soiled
Heavy



10: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK