COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BG19BDU

Iveco Daily 50-150

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Code	999900

Details

Location	Bedford	**GVW**	5200kg	**MOT Due**	30/06/2027
Reg. date	05/03/2019	**Colour**	WHITE	**Cab Type**	DAY CAB
Year	2019	**VIN**	ZCFC150B005217648	**Gearbox**	MANUAL
Mileage	93,066 Km Warranted	**Body Style**	Access Platform	**Axle Combi**	4x2
Fuel Type	DIESEL	**Service history**	Yes	**Rear Suspension**	Steel

WARNING LIGHT ON DASH VERSALIFT ETM38-F PLATFORM

Tyres


NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Park assist camera

Photos
































Commercial Vehicle Auctions Limited



Condition Check



Damage Photos



1: Carpets Front
Holed
Over 3mm



2: Panel Front
Dented
Between 10mm + 30mm



3: Panel Front
Scratched
UpTo 25mm Thru Paint



4: Door nsf
Chipped
Over 5mm



5: Qtr Panel osr
Dented
Over 30mm



6: Qtr Panel osr
Dented
Over 30mm



7: Door osf
Chipped
Over 5mm

Interior

Carpet Condition	Poor	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK