

VEHICLE INSPECTION REPORT

C438833

LAWRENCE DAVID BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Bedford	Colour	WHITE	Rear Suspension	Air
Reg. date	01/01/2016	VIN	SDCPL45B300151965	Rear Doors	Roller
Year	2016	Body Style	Trailer	Tail Lift	Tuckaway
Mileage	Not Showing	MOT Due	30/11/2026		
Fuel Type		Axle Combi	Tri		

BPW AXLES, FERRY LASHING RINGS, RAISE & LOWER VALVE

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



