COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

KX19AYZ

Isuzu D-Max 2.5

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	24961
Cap Code	ISDM25 PDTM4 L

Details

Location	Bedford	**Colour**	WHITE	**MOT Due**	27/04/2027
Reg. date	14/06/2019	**VIN**	MPATFS87JJT010088	**Gearbox**	MANUAL
Year	2019	**Body Style**	Access Platform	**Gears**	6
Mileage	77,640 Miles Warranted	**Service history**	Yes	**Axle Combi**	4x4
		Last service date	22/04/2026		
Fuel Type	DIESEL	**Last service miles**	72,335		
GVW	3500kg				

WARNING LIGHT ON DASH PALFINGER P130 PLATFORM (YEAR 2019)

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Park assist camera
- Air conditioning
- Front electric windows


Photos
















PALFINGER
Head Office:
Piazza G.Verdi 43
39100 - Bolzano (Italy)
Operational Headquarters
Via E.De Nicola 31
41122 - Modena (Italy)
MODEL: P 130 A KIT
TYPE: KIT
SERIAL NUMBER: 44130414
CONSTRUCTION YEAR: 2019
MAX CAPACITY: Kg 240 MAX N° 2 PEOPLE
MAX HORIZONTAL LOAD: daN 40
MAX WIND SPEED: m/s 12,5
MAX PRESSURE HYDRAULIC: bar 210
MAX PERMISSIBLE CHASSIS INCLINATION: 5,0 °(Degree)
ELECTRICAL VOLTAGE: V 12 (dc)


ISUZU MOTORS LTD.
e4*2007/46*0413
GVW 3050 kg
GCW 6000 kg
AXLE 1 1350 kg
AXLE 2 1870 kg



















Condition Check



Damage Photos



1: Bumper Front
Dented
Between 10mm + 30mm



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Bumper Rear
Rusted
Over 5mm



9: B Post os
Dented
Between 10mm + 30mm



10: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault