COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

KU10VKR

Daf LF 55.220

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Code	999900

Details

Location	Bedford	**GVW**	18000kg	**Cab Type**	DAY CAB
Reg. date	12/04/2010	**Colour**	WHITE	**Gearbox**	MANUAL
Year	2010	**VIN**	XLRAE55GF0L343452	**Axle Combi**	4x2
Mileage	333,047 Km Warranted	**Body Style**	Skiploader	**Rear Suspension**	Steel
Fuel Type	DIESEL	**MOT Due**	30/11/2026		

FUEL TANK NOT STRUCTURALLY SOUND SURROUND CAMERA SYSTEM, SHEETING SYSTEM

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Park assist camera

Photos












VDO
14:11
333048.0


VDL
KUIO VKR


LEYLAND DAF
RIGID
12/04/10
2008
18000
19000
21500
22500
7100
7500
11500
DEPARTMENT FOR
TRANSPORT
GREAT BRITAIN
REPLACEMENT


DAF TRUCKS N.V.
ENG. TYPE
058T104T
XLRAE55GF0L343452
TYPE
18000
19000
kg
21500
22500
kg
1- 7100
7500
kg
2- 11500
11500
kg
3-
kg
4-
kg
DAF





www.transcover.com
PS.13TON
70348
2008.01
320
13
VDL
containersystemen














Condition Check



Damage Photos



1: Door osf
Dented
With Paint Damage




2: Wing osf
Dented
With Paint Damage



3: Wing osf
Scratched
UpTo 25mm Thru Paint



4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Dented
With Paint Damage

Interior

Carpet Condition	-	**Upholstery Condition**	-
Seat Condition	-	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK