



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YO22RXB

Scania P 410

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Doncaster

Reg. date 01/06/2022

Year 2022

Mileage 173,745 Km Not Warranted

Fuel Type Diesel

GVW 32000kg

Colour RED

VIN YS2P8X40005650970

Body Style Tipper Grab

Service history None

MOT Due 31/07/2027

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x4

Rear Suspension Steel

WARNING LIGHT ON DASH THOMPSON BULK BODY, PALFINGER ESPILON M215L C82 REMOTE CRANE (YEAR 2021)


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4



Features

- Bluetooth connection
- Cruise control
- Navigation system
- Park assist camera
- Auxiliary input socket
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Panel Front
Dented
With Paint Damage



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door Mirror Assy nsf
Broken
Replace



4: B Post ns
Dented
With Paint Damage



5: Door osf
Scratched
Over 25mm Thru Paint



6: Dash Warning Lights
Displayed
No Action



7: Seat Base Cover osf
Torn
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK